

Autodesk Inventor 2011 for Engineers & Designers

CADCIM Technologies

*525 St. Andrews Drive
Schererville, IN 46375, USA
(www.cadcim.com)*

Contributing Authors

Sham Tickoo

*Professor
Department of Mechanical Engineering Technology
Purdue University Calumet
Hammond, Indiana, USA*

Surinder Raina

*Sr. CAD Engineer
CADSoft Technologies*



DEDICATION

*To teachers, who make it possible to disseminate knowledge
to enlighten the young and curious minds
of our future generations*

*To students, who are dedicated to learning new technologies
and making the world a better place to live in*

SPECIAL RECOGNITION

*A special thanks to Mr. Denis Cadu and the ADN team of Autodesk Inc.
for their valuable support and professional guidance to
procure the software for writing this textbook*

THANKS

*To the faculty and students of the MET department of
Purdue University Calumet for their cooperation*

To Sandeep Prem Dass for technically editing this manuscript

To Anju Jethwani, Sudam C. Mishra, and Rajendra Badola for copy editing this manuscript

Online Training Program Offered by CADCIM Technologies

CADCIM Technologies provides effective and affordable virtual online training on various software packages including Computer Aided Design and Manufacturing (CAD/CAM), computer programming languages, animation, architecture, and GIS. The training is delivered 'live' via Internet at any time, any place, and at any pace to individuals, students of colleges, universities, and CAD/CAM training centers. The main features of this program are:

Training for Students and Companies in a Class Room Setting

Highly experienced instructors and qualified Engineers at CADCIM Technologies conduct the classes under the guidance of Prof. Sham Tickoo of Purdue University Calumet, USA. This team has authored several textbooks that are rated "one of the best" in their categories and are used in various colleges, universities, and training centers in North America, Europe, and in other parts of the world.

Training for Individuals

The cost effective and time saving initiative of CADCIM Technologies

strives to deliver the training in the comfort of your home or work place, thereby relieving you from the hassles of traveling to training centers.

Training Offered on Software Packages

We provide basic and advanced training on the following software packages:

CAD/CAM/CAE: CATIA, Pro/ENGINEER Wildfire, SolidWorks, Autodesk Inventor, Solid Edge, NX, AutoCAD, AutoCAD LT, Customizing AutoCAD, EdgeCAM, and ANSYS

Computer Programming: C++, VB.NET, Oracle, AJAX, and Java

Animation and Styling: Autodesk 3ds Max, 3ds Max Design, Maya, and Alias

Architecture and GIS: Autodesk Revit Architecture, Autodesk Civil 3D, Autodesk Revit Structures, and Autodesk Map 3D

For more information, please visit the following link:

<http://www.cadcim.com>

Note

The free teaching and learning resources, mentioned in the cover page of this textbook, are available only for the students who buy the textbook from our web site **www.cadcim.com** or the university/college bookstores. We need proof of purchase when you request the technical support from us.

Table of Contents

Dedication	iii
Preface	xix

Chapter 1: Introduction

Introduction to Autodesk Inventor 2011	1-2
Part Module	1-2
Assembly Module	1-2
Presentation Module	1-3
Drawing Module	1-3
Sheet Metal Module	1-3
Getting Started with Autodesk Inventor	1-3
Quick Access Toolbar	1-7
Ribbon and Tabs	1-7
Sketch Tab	1-8
Model Tab	1-8
Sheet Metal Tab	1-9
Assemble Tab	1-9
Place Views Tab	1-9
Presentation Tab	1-10
Tools Tab	1-10
View Tab	1-10
Navigation Bar	1-11
Browser Bar	1-11
Units for Dimensions	1-12
Important terms and their definitions	1-12
Feature-based Modeling	1-12
Parametric Modeling	1-12
Bidirectional Associativity	1-12
Adaptive	1-13
Design Doctor	1-13
Constraints	1-13
Consumed Sketch	1-15
Cycling Through Entities	1-16
Hotkeys	1-16
Part Module	1-16
Assembly Module	1-17
Drawing Module	1-18
Customizing Hotkeys	1-18
Creating the Sketch	1-20
Color Scheme	1-20
Self-Evaluation Test	1-21
Review Questions	1-22

Chapter 2: Drawing Sketches for Solid Models

The Sketching Environment	2-2
The Open Dialog Box	2-2
Starting a New File	2-5
Introduction to the Sketching Environment	2-7
Setting Up The Sketching Environment	2-7
Modifying the Document Settings of a Sketch	2-8
Understanding the Drawing Display Tools	2-9
Zoom All	2-10
Zoom Window	2-10
Zoom	2-10
Zoom Selected	2-10
Pan	2-11
Sketching Entities	2-11
Specifying the Position of Entities Dynamically by Using the Dynamic Input <i>New</i>	2-11
Drawing Lines <i>Enhanced</i>	2-12
Drawing Circles	2-15
Drawing Ellipses	2-16
Drawing Arcs <i>Enhanced</i>	2-17
Drawing Rectangles <i>Enhanced</i>	2-19
Drawing Polygons	2-20
Placing Points	2-21
Creating Fillets	2-21
Creating Chamfers	2-22
Drawing Splines	2-24
Creating a Smooth Curve between Two Existing Curves <i>New</i>	2-25
Deleting Sketched Entities	2-26
Deleting Entities by Using a Window	2-26
Deleting Entities by Using a Crossing	2-26
Finishing a Sketch <i>New</i>	2-26
Tutorial 1	2-27
Tutorial 2	2-31
Tutorial 3	2-34
Tutorial 4	2-38
Self-Evaluation Test	2-41
Review Questions	2-42
Exercise 1	2-43
Exercise 2	2-43
Exercise 3	2-44

Chapter 3: Adding Constraints and Dimensions to Sketches

Adding Geometric Constraints to a Sketch	3-2
Perpendicular Constraint	3-2
Parallel Constraint	3-2
Tangent Constraint	3-3
Coincident Constraint	3-3

Concentric Constraint	3-3
Collinear Constraint	3-4
Horizontal Constraint	3-4
Vertical Constraint	3-4
Equal Constraint	3-5
Fix Constraint	3-5
Symmetric Constraint	3-5
Smooth Constraint	3-6
Viewing the Constraints Applied to a Sketched Entity	3-6
Controlling Constraints and Applying them Automatically While Sketching	3-7
Selecting Constraints	3-7
Applying Constraints	3-8
Deleting Geometric Constraints	3-8
Adding Dimensions to Sketches	3-9
Linear Dimensioning	3-9
Aligned Dimensioning	3-11
Angular Dimensioning	3-11
Diameter Dimensioning	3-12
Radius Dimensioning	3-13
Linear Diameter Dimensioning	3-14
Creating Driven Dimensions	3-15
Understanding the Concept of Fully-Constrained Sketches	3-16
Measuring Sketched Entities	3-17
Measuring Distances	3-17
Measuring Angles	3-19
Measuring Loops	3-20
Measuring the Area	3-20
Adding Linear Measurements	3-20
Clearing Accumulated Dimensions	3-21
Evaluating Region Properties	3-21
Tutorial 1	3-22
Tutorial 2	3-26
Tutorial 3	3-31
Tutorial 4	3-36
Self-Evaluation Test	3-39
Review Questions	3-39
Exercise 1	3-41
Exercise 2	3-41
Exercise 3	3-41
Exercise 4	3-42
Exercise 5	3-42

Chapter 4: Editing, Extruding, and Revolving the Sketches

Editing Sketched Entities	4-2
Extending Sketched Entities	4-2
Trimming Sketched Entities	4-2

Splitting Sketched Entities	4-3
Offsetting Sketched Entities	4-4
Mirroring Sketched Entities	4-5
Moving Sketched Entities	4-5
Rotating Sketched Entities	4-9
Creating Patterns	4-10
Creating Rectangular Patterns	4-10
Creating Circular Patterns	4-13
Writing Text in the Sketching Environment	4-16
Writing Regular Text	4-16
Writing Text Aligned to a Geometry	4-19
Inserting Images and Documents in Sketches	4-20
Editing Sketched Entities by Dragging	4-21
Tolerances	4-22
Adding Tolerances to the Dimensions in the Sketching Environment	4-22
Converting the Base Sketch into a Base Feature	4-23
Extruding the Sketch <i>Enhanced</i>	4-24
Revolving the Sketch <i>Enhanced</i>	4-28
Direct Manipulation of Features by Using the Mini Toolbar <i>New</i>	4-30
Selection tag	4-30
Command Options	4-31
Manipulators	4-31
Rotating the View of a Model in 3D Space	4-32
Rotating the View of a Model Using the Orbit	4-32
Changing the View Using the ViewCube	4-33
Navigating the Model	4-36
Controlling the Display of Models	4-37
Setting the Visual Styles <i>Enhanced</i>	4-37
Setting the Shadow Options <i>Enhanced</i>	4-39
Setting the Camera Type	4-40
Tutorial 1	4-40
Tutorial 2	4-45
Tutorial 3	4-47
Tutorial 4	4-51
Self-Evaluation Test	4-54
Review Questions	4-54
Exercise 1	4-56
Exercise 2	4-56
Exercise 3	4-57
Exercise 4	4-57
Exercise 5	4-58

Chapter 5: Other Sketching and Modeling Options

Need for other Sketching Planes	5-2
Defining a New Sketching Plane	5-2
Work Features <i>Enhanced</i>	5-3

Creating Work Planes	5-3
Creating Work Axes	5-13
Creating Work Points	5-16
Other Extrusion Options	5-20
Other Revolution Options	5-25
Operations Area	5-25
Match shape	5-26
The Concept of Sketch Sharing	5-27
Sharing Sketches	5-27
Tutorial 1	5-28
Tutorial 2	5-33
Tutorial 3	5-37
Self-Evaluation Test	5-42
Review Questions	5-43
Exercise 1	5-44
Exercise 2	5-44
Exercise 3	5-45
Exercise 4	5-46

Chapter 6: Advanced Modeling Tools-I

Advanced Modeling Tools	6-2
Creating Holes <i>Enhanced</i>	6-2
Creating Fillets <i>Enhanced</i>	6-12
Creating Edge Fillets	6-12
Creating Face Fillets	6-19
Creating Full Round Fillets	6-20
Creating Chamfers <i>Enhanced</i>	6-22
Mirroring Features and Models	6-24
Creating Rectangular Patterns	6-26
Creating Circular Patterns	6-29
Creating Rib Features	6-31
Thickening or Offsetting the Faces of Features	6-33
Creating the Embossed and Engraved Features	6-37
Applying Images on a Feature	6-39
Assigning Different Colors/styles to a Model	6-40
Tutorial 1	6-40
Tutorial 2	6-46
Tutorial 3	6-53
Tutorial 4	6-59
Self-Evaluation Test	6-63
Review Questions	6-63
Exercise 1	6-64
Exercise 2	6-65

Chapter 7: Editing Features and Adding Automatic Dimensions to Sketches

Concept of Editing Features	7-2
Editing Features of a Model	7-2
Updating Edited Features	7-4
Editing Features Dynamically by Using 3D Grips	7-5
Editing the Sketches of Features	7-6
Redefining the Sketching Plane of a Sketched Feature	7-8
Suppressing Features	7-9
Unsuppressing the Suppressed Features	7-9
Moving the Faces of a Solid <i>Enhanced</i>	7-10
Free Move Method	7-10
Direction and Distance Method	7-11
Points and Plane Method	7-11
Deleting Features	7-11
Copying and Pasting Features	7-12
Adding Automatic Dimensions to Sketches	7-15
Projecting Entities in the Sketching Environment	7-16
Projecting Edges or Faces	7-16
Projecting Cutting Edges	7-17
Tutorial 1	7-17
Tutorial 2	7-24
Tutorial 3	7-28
Self-Evaluation Test	7-34
Review Questions	7-35
Exercise 1	7-36
Exercise 2	7-37
Exercise 3	7-38
Exercise 4	7-38
Exercise 5	7-39

Chapter 8: Advanced Modeling Tools-II

Advanced Modeling Tools	8-2
Creating Sweep Features	8-2
Creating Lofted Features	8-8
Creating Coil Features	8-18
Creating Threads	8-22
Creating Shell Features	8-25
Applying Drafts	8-27
Creating Split Features	8-29
Trimming Surfaces	8-31
Extending Surfaces	8-33
Deleting Faces	8-34
Replacing Faces with Surfaces	8-36
Creating Planar Boundary Patches	8-37
Stitching Surfaces	8-39

Working with the Sculpt Tool	8-40
Working with the Bend Part Tool	8-41
Reordering the Features	8-44
Using the Sketch Doctor	8-45
Using the Design Doctor	8-46
Tutorial 1	8-47
Tutorial 2	8-51
Tutorial 3	8-53
Tutorial 4	8-55
Tutorial 5	8-58
Self-Evaluation Test	8-61
Review Questions	8-61
Exercise 1	8-62
Exercise 2	8-63

Chapter 9: Assembly Modeling-I

Assembly Modeling	9-2
Types of Assemblies	9-2
Top-down Assemblies	9-3
Bottom-up Assemblies	9-3
Creating Top-down Assemblies	9-4
Creating Components in the Assembly Module	9-4
Creating Bottom-Up Assemblies	9-7
Placing Components in the Assembly File	9-7
Assembling Components by Using the Constrain Tool	9-8
Mate Constraint	9-9
Angle Constraint	9-11
Tangent Constraint	9-13
Insert Constraint	9-13
Rotation Constraint	9-14
Rotation-Translation Constraint	9-15
Transitional Constraint	9-16
Specifying the Limits for Constraining <i>New</i>	9-16
Name	9-16
Use Offset As Resting Position	9-16
Maximum	9-17
Minimum	9-17
Assembling Parts by Using the Assemble Tool <i>New</i>	9-17
Using ALT+Drag to Apply Assembly Constraints	9-18
Moving Individual Components	9-19
Rotating Individual Components in 3D Space	9-19
Tutorial 1	9-20
Tutorial 2	9-35
Tutorial 3	9-42
Self-Evaluation Test	9-51
Review Questions	9-52
Exercise 1	9-53

Chapter 10: Assembly Modeling-II

Editing Assembly Constraints	10-2
Editing Components	10-3
Editing Components in the Assembly File	10-3
Editing Components by Opening their Part Files	10-5
Creating Subassemblies	10-5
Creating a Subassembly Using the Bottom-up Design Approach	10-6
Creating a Subassembly Using the Top-down Design Approach	10-6
Checking Degrees of Freedom of a Component	10-6
Creating the Pattern of Components in an Assembly	10-7
Component	10-8
Associative Tab	10-8
Rectangular Tab	10-9
Circular Tab	10-9
Replacing a Component From the Assembly File with another Component	10-10
Replacing a Single Instance of the Selected Component	10-10
Replacing all Instances of the Selected Component	10-11
Mirroring Subassemblies or Components of An Assembly	10-12
Components	10-12
Mirror Plane	10-12
List Box	10-13
More	10-13
List Box	10-13
Naming Scheme Area	10-14
Component Destination Area	10-15
Return to Selection	10-15
Copying Subassemblies or Components of an Assembly	10-15
Deleting Components	10-16
Editing the Pattern of Components	10-16
Making a Pattern Instance Independent	10-16
Deleting Assembly Constraints	10-17
Creating Assembly Section Views in the Assembly File	10-17
Analyzing Assemblies for Interference	10-18
Creating Design View Representations	10-20
Design View Representation Area	10-21
Simulating the Motion of Components of an Assembly by Driving	
Assembly Constraints	10-21
Start	10-22
End	10-22
Pause Delay	10-22
Forward	10-23
Reverse	10-23
Pause	10-23
Minimum	10-23
Reverse Step	10-23
Forward Step	10-23

Maximum	10-23
Record	10-23
More	10-24
Creating Positional Representations	10-25
Viewing the Bill of Material of the Current Assembly	10-26
Working with Assembly Features	10-27
Tutorial 1	10-28
Tutorial 2	10-30
Tutorial 3	10-32
Self-Evaluation Test	10-38
Review Questions	10-38
Exercise 1	10-39

Chapter 11: Working with Drawing Views-I

The Drawing Module	11-2
Types of Views	11-3
Base View	11-3
Projected View	11-3
Auxiliary View	11-4
Section View	11-4
Detail View	11-4
Broken View	11-4
Break Out View	11-4
Overlay View	11-4
Slice View	11-4
Generating Drawing Views	11-5
Generating the Base View <i>Enhanced</i>	11-5
Generating Projected Views	11-10
Generating Auxiliary Views	11-12
Generating Section Views	11-13
Generating Detail Views	11-14
Generating Broken Views	11-16
Generating Break Out Views	11-18
Generating Overlay Views	11-20
Generating Slice Views	11-22
Drafting Drawing Views	11-23
Editing Drawing Views	11-23
Deleting Drawing Views	11-24
Moving Drawing Views	11-25
Copying Drawing Views	11-25
Rotating Drawing Views	11-25
By Area	11-26
Counter clockwise	11-26
Clockwise	11-26
Assigning Different Hatch Patterns to the Components in Assembly Section Views	11-26

By Material	11-27
Angle	11-27
Line Weight	11-28
Scale	11-28
Shift	11-28
Color	11-28
Double	11-28
Editing the Default Hatch Style of the Sectioned Objects	11-29
Excluding the Components from Assembly Section Views	11-30
Tutorial 1	11-31
Tutorial 2	11-37
Self-Evaluation Test	11-42
Review Questions	11-42
Exercise 1	11-43

Chapter 12: Working with Drawing Views-II

Modifying Drawing Standards	12-2
Inserting Additional Sheets into Drawing	12-3
Activating a Drawing Sheet	12-3
Displaying Dimensions in Drawing Views	12-3
Retrieving Parametric Dimensions in Drawing Views	12-4
Adding Reference Dimensions	12-5
Modifying the Model Dimensions	12-5
Editing Drawing Sheets	12-5
Format Area	12-6
Revision	12-6
Orientation Area	12-6
Options Area	12-6
Creating Dimension Styles	12-7
Applying Dimension Styles	12-8
Modifying a Dimension and its Appearance using the Shortcut Menu	12-8
Adding the Parts List	12-8
Source Area	12-8
BOM Settings and Properties Area	12-10
Table Wrapping Area	12-10
Editing the Parts List	12-11
Column Chooser	12-12
Group Settings	12-12
Filter Settings	12-13
Sort	12-13
Export	12-13
Table Layout	12-13
Renummer Items	12-13
Save Item Overrides to BOM	12-14
Member Selection	12-14
Adding/Removing Custom Parts	12-14

Shortcut Menu Options	12-14
Setting the Standard for the Parts List	12-15
Adding Balloons to Assembly Drawing Views	12-15
Adding Balloons to Selected Components	12-16
Adding Automatic Balloons	12-16
Adding Text to a Drawing Sheet	12-18
Adding Multiline Text without a Leader	12-19
Adding Multiline Text with Leader	12-20
Tutorial 1	12-21
Tutorial 2	12-26
Tutorial 3	12-31
Self-Evaluation Test	12-36
Review Questions	12-36
Exercise 1	12-37

Chapter 13: Presentation Module

The Presentation Module	13-2
Creating the Presentation View	13-3
Assembly Area	13-3
Explosion Method Area	13-4
Defining Units for Presentation Files	13-6
Tweaking Components in the Presentation View	13-6
Create Tweak Area	13-6
Transformations Area	13-8
Clear	13-9
Animating an Assembly	13-9
Rotating the Presentation View Precisely	13-15
Increment	13-15
Rotate Down	13-15
Rotate Up	13-15
Rotate Left	13-15
Rotate Right	13-15
Roll Counter Clockwise	13-15
Roll Clockwise	13-15
Reset	13-15
Tutorial 1	13-16
Tutorial 2	13-23
Self-Evaluation Test	13-30
Review Questions	13-30
Exercise 1	13-31

Chapter 14: Working with Special Design Tools

Adaptive Parts	14-2
Defining Parameters <i>Enhanced</i>	14-2
Model Parameters	14-2

User Parameters	14-4
Update	14-5
Immediate Update	14-5
Link	14-5
Filter	14-6
Working with iParts	14-7
Types of iPart Factories	14-7
Creating iPart Factories	14-7
Procedure to Create an iPart	14-13
Inserting an iPart into an Assembly	14-14
Changing the iParts in the Assembly File	14-17
Creating 3D Sketches	14-18
Line	14-18
Spline	14-19
Bend	14-19
Include Geometry	14-19
Intersection Curve	14-19
Helical Curve	14-19
Tutorial 1	14-21
Tutorial 2	14-25
Tutorial 3	14-29
Tutorial 4	14-33
Tutorial 5	14-36
Self-Evaluation Test	14-43
Review Questions	14-44
Exercise 1	14-45

Chapter 15: Working with Sheet Metal Components

The Sheet Metal Module	15-2
Setting Sheet Metal Component Parameters	15-4
Setting the Sheet Metal Rule	15-4
Setting the Material Style	15-12
Setting the Unfolding Rule	15-12
Creating Sheet Metal Components	15-14
Shape Tab	15-16
Unfold Options Tab	15-18
Bend Tab	15-18
Folding Sheet Metal Components	15-18
Adding Flanges to Sheet Metal Components	15-20
Creating Cuts in Sheet Metal Components	15-25
Creating Seams at the Corners of Sheet Metal Components	15-26
Bending the Faces of a Sheet Metal Component	15-30
Rounding the Corners of Sheet Metal Components	15-33
Corner	15-33
Radius	15-33
Select Mode Area	15-33

Chamfering the Corners of Sheet Metal Components	15-34
One Distance	15-34
Distance and Angle	15-35
Two Distances	15-35
Punching 3D shapes into Sheet Metal Components	15-35
Preview Tab	15-36
Geometry Tab	15-37
Size Tab	15-37
Creating Hems	15-38
Creating Contour Flanges	15-40
Creating the Flat Patterns of Sheet Metal Components	15-42
Adding or Removing Material from the Flat Pattern	15-43
Tutorial 1	15-44
Tutorial 2	15-50
Self-Evaluation Test	15-56
Review Questions	15-57
Exercise 1	15-58

Chapter 16: Introduction to Weldments

Understanding Weldment Assemblies	16-2
Main Types of Welds in Autodesk Inventor	16-3
Cosmetic Welds	16-3
Fillet Welds	16-4
Groove Welds	16-5
Adding Welds to Assemblies	16-5
Assembling the Components of Weldment Assemblies	16-6
Preparing Assemblies for Weldments	16-6
Adding Welds	16-6
Creating Fillet Welds	16-6
Bead Area	16-6
Contour Area	16-7
Intermittency Area	16-7
Extents Area	16-7
Create Welding Symbol	16-8
Creating Cosmetic Welds	16-8
Bead Area	16-9
Creating Groove Welds	16-10
Bead Area	16-10
Tutorial 1	16-11
Tutorial 2	16-16
Self-Evaluation Test	16-20
Review Questions	16-21
Exercise 1	16-22

Chapter 17: Miscellaneous Tools

Introduction	17-2
Copying the Sketches	17-2
Scaling the Sketches	17-3
Finding the Center of Gravity	17-3
Extracting the iFeature	17-4
Type Area	17-4
Selected Features Area	17-5
Size Parameters Area	17-5
Position Geometry Area	17-5
Manufacturing Area	17-5
Depth Area	17-6
Inserting the iFeature	17-6
Select	17-6
Position	17-6
Size	17-7
Precise Pos.	17-7
Creating iMates	17-7
Name Area	17-8
Limits Tab	17-8
Matching Tab	17-8
Applying iMates in the Assembly Environment	17-9
Interactively place with iMates	17-9
Automatically generate iMates on place	17-9
Viewing the iProperties	17-9
General Tab	17-9
Summary Tab	17-10
Project Tab	17-10
Status Tab	17-10
Custom Tab	17-11
Save Tab	17-11
Physical Tab	17-11
Creating User-Defined Drawing Sheets	17-11
Sheet Formats	17-11
Borders	17-11
Title Blocks	17-13
Creating Sketch Symbols	17-17
Importing AutoCAD Blocks into Inventor New	17-18
Tutorial 1	17-20
Tutorial 2	17-25
Self-Evaluation Test	17-28
Review Questions	17-29
Exercise 1	17-30