

Creo Parametric 1.0

for Engineers and Designers

CADCIM Technologies

*525 St. Andrews Drive
Schererville, IN 46375, USA
(www.cadcim.com)*

Contributing Author

Sham Tickoo

*Professor
Department of Mechanical Engineering Technology
Purdue University Calumet
Hammond, Indiana
USA*

Gaurav Verma

*CAD Engineer
CADSoft Technologies*



DEDICATION

*To teachers, who make it possible to disseminate knowledge
to enlighten the young and curious minds
of our future generations*

*To students, who are dedicated to learning new technologies
and making the world a better place to live in*

THANKS

*To the faculty and students of the MET department of
Purdue University Calumet for their cooperation*

*To **Gaganjeet Singh Sethi** and **Amit Bhatt** for Technically Editing this manuscript*

*To **Monica Swaroop** and **Gunanidhi Mahapatra** for Copy Editing this manuscript*

Online Training Program Offered by CADCIM Technologies

CADCIM Technologies provides effective and affordable virtual online training on various software packages including Computer Aided Design and Manufacturing (CAD/CAM), computer programming languages, animation, architecture, and GIS. The training is delivered 'live' via Internet at any time, any place, and at any pace to individuals, students of colleges, universities, and CAD/CAM training centers. The main features of this program are:

Training for Students and Companies in a Class Room Setting

Highly experienced instructors and qualified Engineers at CADCIM Technologies conduct the classes under the guidance of Prof. Sham Tickoo of Purdue University Calumet, USA. This team has authored several textbooks that are rated "one of the best" in their categories and are used in various colleges, universities, and training centers in North America, Europe, and in other parts of the world.

Training for Individuals

The cost effective and time saving initiative of CADCIM Technologies

strives to deliver the training in the comfort of your home or work place, thereby relieving you from the hassles of traveling to training centers.

Training Offered on Software Packages

We provide basic and advanced training on the following software packages:

CAD/CAM/CAE: CATIA, Creo Parametric, SolidWorks, Autodesk Inventor, Solid Edge, NX, AutoCAD, AutoCAD LT, Customizing AutoCAD, EdgeCAM, and ANSYS

Computer Programming Languages: C++, VB.NET, Oracle, AJAX, and Java

Animation and Styling: Autodesk 3ds Max, 3ds Max Design, Maya, Alias Design, Adobe Flash, and Adobe Premiere.

Civil, Architecture, and GIS: Autodesk Revit Architecture, AutoCAD Civil 3D, and AutoCAD Map 3D

For more information, please visit the following link:

<http://www.cadcim.com>

Note

If you are a faculty member, you can register by clicking on the following link to access the teaching resources: **<http://www.cadcim.com/Registration.aspx>**. The student resources are available at **<http://www.cadcim.com>**. We also provide **Live Virtual Online Training** on various software packages. For more information, write us at **sales@cadcim.com**.

Table of Contents

| | |
|-------------------|-----|
| Dedication | iii |
| Preface | xv |

Chapter 1: Introduction to Creo Parametric 1.0

| | |
|--|------|
| Introduction to Creo Parametric 1.0 | 1-2 |
| Feature-Based Nature | 1-2 |
| Bidirectional Associative Property | 1-3 |
| Parametric Nature | 1-4 |
| System Requirements | 1-6 |
| Getting Started with Creo Parametric | 1-7 |
| Important Terms and Definitions | 1-7 |
| File Menu Options | 1-9 |
| Managing Files | 1-19 |
| Menu Manager | 1-20 |
| Model Tree | 1-20 |
| Understanding the Functions of the Mouse Buttons | 1-21 |
| Ribbon | 1-22 |
| Toolbars | 1-22 |
| Navigator | 1-25 |
| Creo Parametric Browser | 1-26 |
| Appearance Gallery | 1-27 |
| Rendering in Creo Parametric | 1-29 |
| Color Scheme Used in this Book | 1-32 |

Chapter 2: Creating Sketches in the Sketch Mode-I

| | |
|--|------|
| The Sketch Mode | 2-2 |
| Working with the Sketch Mode | 2-2 |
| Invoking the Sketch Mode | 2-3 |
| The Sketcher Environment | 2-3 |
| Working with a Sketch in the Sketch Mode | 2-4 |
| Drawing a Sketch Using tools available in the Sketch Tab | 2-5 |
| Placing a Point | 2-5 |
| Drawing a Line | 2-5 |
| Drawing a Centerline | 2-7 |
| Drawing a Geometry Centerline | 2-8 |
| Drawing a Rectangle | 2-8 |
| Drawing a Circle | 2-9 |
| Drawing an Ellipse | 2-12 |
| Drawing an Arc | 2-13 |
| Dimensioning the Sketch | 2-16 |
| Converting a Weak Dimension into a Strong Dimension | 2-16 |
| Dimensioning a Sketch Using the Normal Tool | 2-17 |

| | |
|--|------|
| Dimensioning the Basic Sketched Entities | 2-17 |
| Linear Dimensioning of a Line | 2-17 |
| Angular Dimensioning of an Arc | 2-18 |
| Diameter Dimensioning | 2-18 |
| Radial Dimensioning | 2-19 |
| Dimensioning Revolved Sections | 2-19 |
| Working With Constraints | 2-19 |
| Types of Constraints | 2-20 |
| Disabling Constraints | 2-21 |
| Modifying the Dimensions of a Sketch | 2-21 |
| Using the Modify Button | 2-21 |
| Modifying a Dimension by Double-Clicking on it | 2-22 |
| Modifying Dimensions Dynamically | 2-22 |
| Resolve Sketch Dialog Box | 2-22 |
| Deleting the Sketched Entities | 2-23 |
| Trimming the Sketched Entities | 2-23 |
| Mirroring the Sketched Entities | 2-24 |
| Inserting Standard/User-Defined Sketches | 2-25 |
| Drawing Display Options | 2-26 |
| Tutorial 1 | 2-28 |
| Tutorial 2 | 2-34 |
| Tutorial 3 | 2-39 |
| Self-Evaluation Test | 2-43 |
| Review Questions | 2-44 |
| Exercise 1 | 2-44 |
| Exercise 2 | 2-45 |
| Exercise 3 | 2-45 |
| Exercise 4 | 2-46 |

Chapter 3: Creating Sketches in the Sketch Mode-II

| | |
|---|------|
| Dimensioning the Sketch | 3-2 |
| Dimensioning a Sketch Using the Baseline Tool | 3-2 |
| Replacing the Dimensions of a Sketch Using the Replace Tool | 3-3 |
| Creating Fillets | 3-3 |
| Creating Circular Fillets | 3-3 |
| Creating Elliptical Fillets | 3-6 |
| Creating a Reference Coordinate System | 3-7 |
| Working with Splines | 3-7 |
| Creating a Spline | 3-8 |
| Dimensioning of Splines | 3-8 |
| Modifying a Spline | 3-10 |
| Writing Text in the Sketcher Environment | 3-11 |
| Rotating and Resizing Entities | 3-12 |
| Importing 2D Drawings in the Sketch Mode | 3-13 |
| Tutorial 1 | 3-14 |
| Tutorial 2 | 3-19 |

| | |
|----------------------|------|
| Tutorial 3 | 3-23 |
| Self-Evaluation Test | 3-27 |
| Review Questions | 3-28 |
| Exercise 1 | 3-29 |
| Exercise 2 | 3-29 |
| Exercise 3 | 3-30 |

Chapter 4: Creating Base Features

| | |
|---|------|
| Creating Base Features | 4-2 |
| Invoking the Part Mode | 4-2 |
| The Default Datum Planes | 4-3 |
| Creating a Protrusion | 4-4 |
| Extruding a Sketch | 4-5 |
| Revolving a Sketch | 4-15 |
| Understanding the Orientation of Datum Planes | 4-16 |
| Parent-Child Relationship | 4-21 |
| Implicit Relationship | 4-21 |
| Explicit Relationship | 4-21 |
| Nesting of Sketches | 4-22 |
| Tutorial 1 | 4-23 |
| Tutorial 2 | 4-29 |
| Tutorial 3 | 4-34 |
| Tutorial 4 | 4-39 |
| Self-Evaluation Test | 4-48 |
| Review Questions | 4-49 |
| Exercise 1 | 4-50 |
| Exercise 2 | 4-50 |
| Exercise 3 | 4-51 |
| Exercise 4 | 4-51 |
| Exercise 5 | 4-52 |

Chapter 5: Datums

| | |
|---|------|
| Datums | 5-2 |
| Default Datum Planes | 5-2 |
| Need for Datums in Modeling | 5-2 |
| Selection Method in Creo Parametric | 5-3 |
| Datum Options | 5-5 |
| Datum Planes | 5-5 |
| Creating Datum Planes | 5-7 |
| Datum Planes Created On-The-Fly | 5-13 |
| Datum Axes | 5-14 |
| Datum Points | 5-19 |
| Creating Cuts | 5-24 |
| Removing Material by Using the Extrude Tool | 5-25 |
| Removing Material by Using the Revolve Tool | 5-26 |

| | |
|----------------------|------|
| Tutorial 1 | 5-27 |
| Tutorial 2 | 5-36 |
| Tutorial 3 | 5-44 |
| Self-Evaluation Test | 5-50 |
| Review Questions | 5-51 |
| Exercise 1 | 5-52 |
| Exercise 2 | 5-53 |
| Exercise 3 | 5-53 |
| Exercise 4 | 5-55 |

Chapter 6: Options Aiding Construction of Parts-I

| | |
|--|------|
| Options Aiding Construction of Parts | 6-2 |
| Creating Holes | 6-2 |
| The Hole Dashboard | 6-2 |
| Important Points to Remember While Creating a Hole | 6-14 |
| Creating Rounds | 6-14 |
| Creating Basic Rounds | 6-15 |
| Creating a Variable Radius Round | 6-23 |
| Points to Remember While Creating Rounds | 6-24 |
| Creating Chamfers | 6-24 |
| Corner Chamfer | 6-24 |
| Edge Chamfer | 6-25 |
| Understanding Ribs | 6-29 |
| Creating Trajectory Ribs | 6-30 |
| Creating Profile Ribs | 6-31 |
| Editing Features of a Model | 6-33 |
| Editing Definition or Redefining Features | 6-34 |
| Reordering Features | 6-34 |
| Rerouting Features | 6-36 |
| Suppressing Features | 6-36 |
| Deleting Features | 6-37 |
| Modifying Features | 6-37 |
| Tutorial 1 | 6-39 |
| Tutorial 2 | 6-48 |
| Tutorial 3 | 6-54 |
| Tutorial 4 | 6-59 |
| Self-Evaluation Test | 6-67 |
| Review Questions | 6-68 |
| Exercise 1 | 6-69 |
| Exercise 2 | 6-70 |

Chapter 7: Options Aiding Construction of Parts-II

| | |
|---------------------------|-----|
| Introduction | 7-2 |
| Creating Feature Patterns | 7-2 |

| | |
|-------------------------------------|------|
| Uses of Patterns | 7-2 |
| Creating Patterns | 7-2 |
| Deleting a Pattern | 7-16 |
| Copying Features | 7-16 |
| New Refs | 7-16 |
| Same Refs | 7-17 |
| Mirror | 7-17 |
| Move | 7-18 |
| Select | 7-18 |
| Mirroring a Geometry | 7-19 |
| Creating a Section of a Solid Model | 7-20 |
| Work Region Method | 7-21 |
| Tutorial 1 | 7-22 |
| Tutorial 2 | 7-28 |
| Tutorial 3 | 7-38 |
| Tutorial 4 | 7-44 |
| Self-Evaluation Test | 7-59 |
| Review Questions | 7-60 |
| Exercise 1 | 7-61 |
| Exercise 2 | 7-62 |
| Exercise 3 | 7-63 |
| Exercise 4 | 7-64 |

Chapter 8: Advanced Modeling Tools-I

| | |
|--|------|
| Other Protrusion Options | 8-2 |
| Sweep Features | 8-2 |
| Creating Sweep Protrusions | 8-2 |
| Aligning a Sketched Trajectory to an Existing Geometry | 8-3 |
| Creating a Thin Sweep Protrusion | 8-3 |
| Creating a Sweep Cut | 8-4 |
| Blend Features | 8-4 |
| Parallel Blend | 8-5 |
| Rotational Blend | 8-7 |
| General Blend | 8-9 |
| Using Blend Vertex | 8-9 |
| Shell Feature | 8-9 |
| Creating a Constant Thickness Shell | 8-11 |
| Creating a Variable Thickness Shell | 8-12 |
| Datum Curves | 8-13 |
| Creating a Datum Curve by Using the Curve Button | 8-13 |
| Creating a Datum Curve by Sketching | 8-16 |
| Creating a Curve by Using the Intersect Option | 8-16 |
| Creating a Curve by Using the Project Option | 8-18 |
| Creating a Curve by Using the Wrap Option | 8-20 |
| Creating Draft Features | 8-22 |
| Tutorial 1 | 8-30 |

| | |
|----------------------|------|
| Tutorial 2 | 8-37 |
| Tutorial 3 | 8-44 |
| Tutorial 4 | 8-50 |
| Self-Evaluation Test | 8-54 |
| Review Questions | 8-55 |
| Exercise 1 | 8-56 |
| Exercise 2 | 8-56 |
| Exercise 3 | 8-57 |
| Exercise 4 | 8-58 |

Chapter 9: Advanced Modeling Tools-II

| | |
|---|------|
| Advanced Feature Creation Tools | 9-2 |
| Variable Section Sweep Using the Sweep Option | 9-2 |
| Swept Blend | 9-6 |
| Helical Sweep | 9-9 |
| Blend Section To Surfaces | 9-11 |
| Blend Between Surfaces | 9-11 |
| Tutorial 1 | 9-13 |
| Tutorial 2 | 9-18 |
| Tutorial 3 | 9-29 |
| Tutorial 4 | 9-35 |
| Self-Evaluation Test | 9-38 |
| Review Questions | 9-39 |
| Exercise 1 | 9-40 |
| Exercise 2 | 9-40 |
| Exercise 3 | 9-42 |
| Exercise 4 | 9-44 |

Chapter 10: Advanced Modeling Tools-III

| | |
|-------------------------|-------|
| Advanced Modeling Tools | 10-2 |
| Toroidal Bend | 10-2 |
| Spinal Bend | 10-3 |
| Warp | 10-5 |
| Transform Tool | 10-6 |
| Warp Tool | 10-8 |
| Spine Tool | 10-10 |
| Stretch Tool | 10-11 |
| Bend Tool | 10-12 |
| Twist Tool | 10-13 |
| Sculpt Tool | 10-14 |
| Tutorial 1 | 10-16 |
| Tutorial 2 | 10-22 |
| Tutorial 3 | 10-25 |
| Self-Evaluation Test | 10-31 |
| Review Questions | 10-32 |

| | |
|------------|-------|
| Exercise 1 | 10-33 |
| Exercise 2 | 10-34 |

Chapter 11: Assembly Modeling

| | |
|--|-------|
| Assembly Modeling | 11-2 |
| Important Terms Related to the Assembly Mode | 11-2 |
| Top-down Approach | 11-2 |
| Bottom-up Approach | 11-3 |
| Placement Constraints | 11-4 |
| Package | 11-4 |
| Creating Top-down Assemblies | 11-4 |
| Creating Components in the Assembly Mode | 11-5 |
| Creating Bottom-up Assemblies | 11-5 |
| Inserting Components in an Assembly | 11-5 |
| Assembling Components | 11-6 |
| Displaying Components in a Separate Window | 11-6 |
| Displaying Components in the Same Window | 11-7 |
| 3D Dragger | 11-7 |
| Applying Constraints | 11-7 |
| Status Area | 11-11 |
| Placement Tab | 11-11 |
| Move Tab | 11-12 |
| Packaging Components | 11-13 |
| Creating Simplified Representations | 11-15 |
| Redefining the Components of an Assembly | 11-19 |
| Reordering Components | 11-19 |
| Suppressing/Resuming Components | 11-19 |
| Replacing Components | 11-20 |
| Assembling Repeated Copies of a Component | 11-21 |
| Modifying the Components of an Assembly | 11-22 |
| Modifying Dimensions of a Feature of a Component | 11-22 |
| Redefining a Feature of a Component | 11-22 |
| Creating the Exploded State | 11-23 |
| References Tab | 11-24 |
| Offset Tab | 11-24 |
| Explode Line Tab | 11-25 |
| The Bill of Materials | 11-27 |
| Global Interference | 11-28 |
| Pairs Clearance | 11-29 |
| Tutorial 1 | 11-30 |
| Tutorial 2 | 11-43 |
| Self-Evaluation Test | 11-53 |
| Review Questions | 11-54 |
| Exercise 1 | 11-55 |
| Exercise 2 | 11-58 |

Chapter 12: Generating, Editing, and Modifying the Drawing Views

| | |
|---|-------|
| The Drawing Mode | 12-2 |
| Generating Drawing Views | 12-4 |
| Generating the General View | 12-4 |
| Generating the Projection View | 12-6 |
| Generating the Detailed View | 12-7 |
| Generating the Auxiliary View | 12-8 |
| Generating the Revolved Section View | 12-8 |
| Generating the Copy and Align View | 12-19 |
| Generating the 3D Cross-Section View | 12-20 |
| Editing the Drawing Views | 12-22 |
| Moving the Drawing View | 12-22 |
| Erasing the Drawing View | 12-23 |
| Deleting the Drawing View | 12-23 |
| Adding New Parts or Assemblies to the Current Drawing | 12-23 |
| Modifying the Drawing Views | 12-24 |
| Changing the View Type | 12-24 |
| Changing the View Scale | 12-25 |
| Reorienting the Views | 12-25 |
| Modifying the Cross-sections | 12-25 |
| Modifying Boundaries of Views | 12-25 |
| Adding or Removing the Cross-section Arrows | 12-25 |
| Modifying the Perspective Views | 12-26 |
| Modifying Other Parameters | 12-26 |
| Editing the Cross-section Hatching | 12-26 |
| Tutorial 1 | 12-26 |
| Tutorial 2 | 12-35 |
| Self-Evaluation Test | 12-41 |
| Review Questions | 12-42 |
| Exercise 1 | 12-43 |

Chapter 13: Dimensioning the Drawing Views

| | |
|--|-------|
| Dimensioning the Drawing Views | 13-2 |
| Show Model Annotations Dialog Box | 13-2 |
| Adding Notes to the Drawing | 13-5 |
| Adding Tolerances in the Drawing Views | 13-5 |
| Dimensional Tolerances | 13-5 |
| Geometric Tolerances | 13-6 |
| Editing the Geometric Tolerances | 13-10 |
| Adding Balloons to the Assembly Views | 13-10 |
| Adding Reference Datums to the Drawing Views | 13-11 |
| Modifying and Editing Dimensions | 13-11 |
| Modifying the Dimensions Using the Dimension Properties Dialog Box | 13-12 |
| Modifying the Drawing Items Using the Shortcut Menu | 13-17 |
| Cleaning Up the Dimensions | 13-18 |

| | |
|----------------------|-------|
| Tutorial 1 | 13-21 |
| Tutorial 2 | 13-27 |
| Self-Evaluation Test | 13-32 |
| Review Questions | 13-32 |
| Exercise 1 | 13-34 |

Chapter 14: Other Drawing Options

| | |
|---|-------|
| Sketching in the Drawing Mode | 14-2 |
| Modifying the Sketched Entities | 14-4 |
| User-Defined Drawing Formats | 14-10 |
| Retrieving the User-Defined Formats in the Drawings | 14-11 |
| Adding and Removing Sheets in the Drawing | 14-12 |
| Creating Tables in the Drawing Mode | 14-12 |
| Generating the BOM and Balloons in Drawings | 14-14 |
| Tutorial 1 | 14-18 |
| Tutorial 2 | 14-28 |
| Self-Evaluation Test | 14-38 |
| Review Questions | 14-38 |
| Exercise 1 | 14-40 |

Chapter 15: Surface Modeling

| | |
|--|-------|
| Surface Modeling | 15-2 |
| Creating Surfaces in Creo Parametric | 15-2 |
| Creating an Extruded Surface | 15-2 |
| Creating a Revolved Surface | 15-3 |
| Creating a Sweep Surface | 15-4 |
| Creating a Blended Surface | 15-4 |
| Creating a Swept Blend Surface | 15-5 |
| Creating a Helical Sweep Surface | 15-6 |
| Creating a Surface by Blending the Boundaries | 15-6 |
| Creating a Variable Section Sweep Surface Using the Sweep Tool | 15-9 |
| Creating Surfaces the Using the Style Environment of Creo Parametric | 15-9 |
| Style Dashboard | 15-10 |
| Surface Editing Tools | 15-17 |
| Mirroring the Surfaces | 15-17 |
| Merging the Surfaces | 15-18 |
| Trimming the Surfaces | 15-19 |
| Creating the Fill Surfaces | 15-20 |
| Creating the Intersect Curves | 15-21 |
| Creating the Offset Surfaces | 15-22 |
| Adding Thickness to a Surface | 15-25 |
| Converting a Surface into a Solid | 15-26 |
| Creating a Round at the Vertex of a Surface | 15-26 |

| | |
|--------------------------------|-------|
| Freestyle Modeling Environment | 15-27 |
| Freestyle Dashboard | 15-27 |
| Tutorial 1 | 15-32 |
| Tutorial 2 | 15-41 |
| Tutorial 3 | 15-49 |
| Self-Evaluation Test | 15-54 |
| Review Questions | 15-55 |
| Exercise 1 | 15-56 |
| Exercise 2 | 15-57 |
| Exercise 3 | 15-58 |

Chapter 16: Working with Sheetmetal Components

| | |
|--|------------|
| Introduction to Sheetmetal | 16-2 |
| Invoking the Sheetmetal Mode | 16-2 |
| Introduction to Sheetmetal Walls | 16-3 |
| Creating the Planar Wall | 16-4 |
| Creating the Unattached Revolve Wall | 16-5 |
| Creating the Unattached Blend Wall | 16-6 |
| Creating the Unattached Offset Wall | 16-9 |
| Creating Reliefs in Sheetmetal Components | 16-10 |
| Creating a Flat Wall | 16-11 |
| Creating a Twist Wall | 16-15 |
| Creating an Extend Wall | 16-17 |
| Creating a Flange Wall | 16-18 |
| Creating the Bend Feature | 16-21 |
| Creating the Unbend Feature | 16-27 |
| Creating the Bend Back | 16-28 |
| Conversion to Sheetmetal Part | 16-29 |
| Creating Cuts in the Sheetmetal Components | 16-31 |
| Creating the Flat Pattern | 16-32 |
| Tutorial 1 | 16-33 |
| Tutorial 2 | 16-42 |
| Self-Evaluation Test | 16-49 |
| Review Questions | 16-49 |
| Exercise 1 | 16-50 |
| Exercise 2 | 16-51 |
| Student Projects | 1 |
| Index | I-1 |