

CATIA V5-6R2013 for Engineers and Designers

Contributing Authors

Sham Tickoo

Professor

*Department of Mechanical Engineering Technology
Purdue University Calumet
Hammond, Indiana, USA*

Avijeet P. Suryavanshi

CAD Engineer

CADSoft Technologies

Table of Contents

Dedication	iii
Preface	xvii

Chapter 1: Introduction to CATIA V5-6R2013

Introduction to CATIA V5-6R2013	1-2
CATIA V5 Workbenches	1-2
System Requirements	1-4
Getting Started with CATIA V5-6R2013	1-4
Important Terms and Definitions	1-6
Understanding the Functions of the Mouse Buttons in CATIA	1-12
Toolbars	1-13
Hot Keys	1-26
Color Scheme	1-27
Self-Evaluation Test	1-29
Review Questions	1-30

Chapter 2: Drawing Sketches in the Sketcher Workbench-I

The Sketcher Workbench	2-2
Starting a New File	2-2
Invoking the Sketcher Workbench	2-4
Invoking the Sketcher Workbench Using the Sketch Tool	2-4
Invoking the Sketcher Workbench Using the Positioned Sketch Tool	2-5
Setting the Sketcher Workbench	2-5
Modifying Units	2-6
Modifying the Grid Settings	2-6
Understanding Sketcher Terms	2-7
Specification Tree	2-7
Grid	2-9
Snap to Point	2-9
Construction/Standard Element	2-9
Select Toolbar	2-9
Inferencing Lines	2-11
Drawing Sketches Using Sketcher Tools	2-12
Drawing Lines	2-12
Drawing Center Lines	2-15
Drawing Rectangles, Oriented Rectangles, and Parallelograms	2-16
Drawing Rectangles	2-16
Creating Points	2-18
Drawing Circles	2-19
Drawing Arcs	2-21
Drawing Profiles	2-23
Drawing Display Tools	2-25
Fit All In	2-25
Pan	2-26

Zoom In	2-26
Zoom Out	2-26
Zoom Area	2-27
Normal View	2-27
Splitting the Drawing Area into Multiple Viewports	2-27
Hiding and Showing Geometric Elements	2-27
Swapping Visible Space	2-28
Tutorial 1	2-28
Tutorial 2	2-32
Tutorial 3	2-36
Tutorial 4	2-40
Self-Evaluation Test	2-45
Review Questions	2-46
Exercise 1	2-47
Exercise 2	2-47
Exercise 3	2-48
Exercise 4	2-48
Exercise 5	2-49
Exercise 6	2-50

Chapter 3: Drawing Sketches in the Sketcher Workbench-II

Other Sketching Tools in the Sketcher Workbench	3-2
Drawing Conics	3-2
Drawing Splines	3-6
Connecting Two Elements by a Spline or an Arc	3-6
Drawing Elongated Holes	3-8
Drawing Cylindrical Elongated Holes	3-8
Drawing Keyhole Profiles	3-9
Drawing Hexagons	3-10
Drawing Centered Rectangles	3-10
Drawing Centered Parallelograms	3-11
Editing and Modifying Sketches	3-11
Trimming Unwanted Sketched Elements	3-12
Extending Sketched Elements	3-13
Trimming by Using the Quick Trim Tool	3-14
Filleting Sketched Elements	3-15
Chamfering Sketched Elements	3-16
Mirroring Sketched Elements	3-17
Mirroring Elements without Duplication	3-18
Translating Sketched Elements	3-18
Rotating Sketched Elements	3-19
Scaling Sketched Elements	3-20
Offsetting Sketched Elements	3-20
Modifying Sketched Elements	3-21
Deleting Sketched Elements	3-24
Tutorial 1	3-24
Tutorial 2	3-29

Tutorial 3	3-33
Self-Evaluation Test	3-37
Review Questions	3-37
Exercise 1	3-38
Exercise 2	3-39
Exercise 3	3-39
Exercise 4	3-40
Exercise 5	3-40

Chapter 4: Constraining Sketches and Creating Base Features

Constraining Sketches	4-2
Concept of Constrained Sketches	4-2
Iso-Constraint	4-2
Under-Constraint	4-2
Over-Constrained	4-3
Inconsistent	4-3
Not Changed	4-3
Applying Geometrical Constraints	4-3
Applying Geometrical Constraints Automatically	4-3
Applying Additional Constraints to the Sketch	4-4
Applying Dimensional Constraints	4-7
Applying Contact Constraints	4-12
Applying Fix Together Constraints	4-12
Applying Auto Constraints	4-13
Editing Multiple Dimensions	4-14
Analyzing and Deleting Over-Defined Constraints	4-15
Analyzing Sketch using the Sketch Analysis Tool	4-16
Exiting the Sketcher Workbench	4-17
Creating Base Features by Extrusion	4-17
Creating a Thin Extruded Feature	4-18
Extruding the Sketch Using the Profile Definition Dialog Box	4-19
Extruding the Sketch along a Directional Reference	4-20
Creating Base Features By Revolving Sketches	4-22
Creating Thin Shaft Features	4-23
Dynamically Rotating the View of the Model	4-23
Rotating the View Using the Rotate Tool	4-24
Rotating the View Using the Compass	4-24
Modifying the View Orientation	4-25
Display Modes of the Model	4-26
Shading (SHD)	4-26
Shading with Edges	4-27
Shading with Edges without Smooth Edges	4-27
Shading with Edges and Hidden Edges	4-27
Shading with Material	4-27
Wireframe (NHR)	4-27
Customize View Parameters	4-27
Creating Sections Dynamically	4-27

Enhanced

Maneuvering the Section Plane	4-28
Position of Section Planes	4-29
Assigning a Material to the Model	4-29
Tutorial 1	4-31
Tutorial 2	4-36
Self-Evaluation Test	4-43
Review Questions	4-44
Exercise 1	4-45
Exercise 2	4-46
Exercise 3	4-47
Exercise 4	4-47

Chapter 5: Reference Elements and Sketch-Based Features

Importance of Sketching Planes	5-2
Reference Elements	5-3
Reference Planes	5-3
Creating New Planes	5-4
Creating Points	5-9
Creating Reference Lines	5-10
Other Sketch-Based Features	5-11
Creating Drafted Filleted Pad Features	5-11
Creating Multi-Pad Features	5-11
Feature Termination Options	5-13
Creating Pocket Features	5-15
Creating Drafted Filleted Pocket Features	5-16
Creating Multi-Pocket Features	5-16
Creating Groove Features	5-17
Extruding and Revolving Planar and Non-planar Faces	5-18
Projecting 3D Elements	5-18
Tutorial 1	5-19
Tutorial 2	5-23
Tutorial 3	5-27
Tutorial 4	5-33
Tutorial 5	5-38
Self-Evaluation Test	5-42
Review Questions	5-43
Exercise 1	5-44
Exercise 2	5-45
Exercise 3	5-46
Exercise 4	5-47

Chapter 6: Creating Dress-Up and Hole Features

Advanced Modeling Tools	6-2
Creating Hole Features	6-2
Creating Fillets	6-10
Creating Chamfers	6-23

Enhanced

Adding a Draft to the Faces of the Model	6-24
Creating a Shell Feature	6-30
Tutorial 1	6-31
Tutorial 2	6-38
Self-Evaluation Test	6-44
Review Questions	6-44
Exercise 1	6-45
Exercise 2	6-46
Exercise 3	6-47

Chapter 7: Editing Features

Editing Features of a Model	7-2
Editing Using the Definition Option	7-2
Editing by Double-Clicking	7-3
Editing the Sketch of a Sketch-Based Feature	7-3
Redefining the Sketch Plane of Sketches	7-3
Deleting Unwanted Features	7-4
Managing Features and Sketches by using the Cut, Copy, and Paste Functionalities	7-5
Understanding the Concept of Update Diagnosis	7-6
Cut, Copy, and Paste Features and Sketches	7-7
Copying Features Using Drag and Drop	7-7
Copying and Pasting PartBodies	7-8
Deactivating Features	7-9
Activating Deactivated Features	7-10
Defining Features in Work Object	7-10
Reordering Features	7-10
Understanding the Parent-Child Relationships	7-12
Measuring Elements	7-12
Measuring between Elements	7-12
Measuring Items	7-14
Measuring Inertia	7-14
Tutorial 1	7-16
Tutorial 2	7-21
Tutorial 3	7-27
Self-Evaluation Test	7-32
Review Questions	7-32
Exercise 1	7-33
Exercise 2	7-34
Exercise 3	7-36

Chapter 8: Transformation Features and Advanced Modeling Tools-I

Transformation Features	8-2
Translating Bodies	8-2
Rotating Bodies	8-3
Creating Symmetry Features	8-5
Transforming the Axis System	8-5

Mirroring Features and Bodies		8-6
Creating Rectangular Patterns	Enhanced	8-8
Creating Circular Patterns		8-13
Creating User Patterns		8-16
Uniform Scaling of Model		8-17
Non-uniform Scaling of Model		8-18
Working With Additional Bodies		8-18
Inserting a New Body		8-19
Inserting Features in the New Body		8-19
Applying Boolean Operations to Bodies		8-19
Adding Stiffeners to a Model		8-25
Generating Solid Combine		8-27
Tutorial 1		8-28
Tutorial 2		8-34
Self-Evaluation Test		8-38
Review Questions		8-38
Exercise 1		8-39
Exercise 2		8-40
Exercise 3		8-41

Chapter 9: Advanced Modeling Tools-II

Advanced Modeling Tools		9-2
Creating Rib Features		9-2
Creating Slot Features		9-7
Creating Multi-Sections Solid Features		9-8
Creating Multi-Sections Solid Cut Features		9-16
Tutorial 1		9-17
Tutorial 2		9-22
Tutorial 3		9-28
Tutorial 4		9-33
Self-Evaluation Test		9-37
Review Questions		9-37
Exercise 1		9-39
Exercise 2		9-40

Chapter 10: Working with the Wireframe and Surface Design Workbench

Need of Surface Modeling		10-2
Wireframe and Surface Design Workbench		10-2
Starting the Wireframe and Surface Design Workbench		10-2
Creating Wireframe Elements		10-2
Creating Circles		10-2
Creating Splines		10-3
Creating a Helix		10-4
Creating Surfaces		10-7
Creating Extruded Surfaces		10-7
Creating Revolved Surfaces		10-8
Creating Spherical Surfaces		10-9

Creating Cylindrical Surfaces	10-9
Creating Offset Surfaces	10-10
Creating Sweep Surfaces	10-11
Creating Fill Surfaces	10-17
Creating Multi-Section Surfaces	10-18
Creating Blended Surfaces	10-19
Operations on Shape Geometry	10-20
Joining Surfaces	10-20
Splitting Surfaces	10-21
Trimming Surfaces	10-22
Tutorial 1	10-23
Tutorial 2	10-30
Self-Evaluation Test	10-39
Review Questions	10-40
Exercise 1	10-41
Exercise 2	10-42

Chapter 11: Editing and Modifying Surfaces

Surface Operations	11-2
Creating Projection Curves	11-2
Creating Intersection Elements	11-3
Healing Geometries	11-5
Disassembling Elements	11-8
Untrimming a Surface or a Curve	11-8
Creating Boundary Curves	11-9
Extracting Geometry	11-11
Transformation	11-11
Extrapolating Surfaces and Curves	11-18
Splitting a Solid Body with a Surface	11-20
Solidifying Surface Models	11-21
Adding Thickness to a Surface	11-21
Creating a Solid Body from a Closed Surface Body	11-21
Sewing a Surface to a Solid Body	11-22
Tutorial 1	11-24
Tutorial 2	11-32
Self-Evaluation Test	11-39
Review Questions	11-39
Exercise 1	11-40

Chapter 12: Assembly Modeling

Assembly Modeling	12-2
Types of Assembly Design Approaches	12-2
Creating Bottom-up Assemblies	12-3
Inserting Components in a Product file	12-4
Moving Individual Components	12-6
Applying Constraints	12-12
Creating Top-down Assemblies	12-22

Creating Base Part in the Top-Down Assembly	12-22
Creating Subsequent Components in the Top-Down Assembly	12-23
Creating Subassemblies in the Top-Down Assembly	12-24
Editing Assemblies	12-25
Deleting Components	12-25
Replacing Components	12-26
Editing Components Inside an Assembly	12-27
Editing Subassemblies Inside an Assembly	12-27
Editing Assembly Constraints	12-28
Simplifying the Assembly	12-29
Interference Detection	12-31
Sectioning an Assembly	12-32
Exploding an Assembly	12-33
Tutorial 1	12-36
Tutorial 2	12-50
Self-evaluation Test	12-57
Review Questions	12-58
Exercise 1	12-59

Chapter 13: Working with the Drafting Workbench-I

The Drafting Workbench	13-2
Starting a New File in the Drafting Workbench	13-2
Type of Views	13-4
Generating Drawing Views	13-6
Generating Views Automatically	13-6
Generating Individual Drawing Views	13-10
Generating the Exploded View	13-25
Working with Interactive Drafting in CATIA V5	13-26
Editing and Modifying Drawing Views	13-27
Changing the Scale of Drawing Views	13-27
Modifying the Project Plane of the Parent View	13-27
Deleting Drawing Views	13-27
Rotating Drawing Views	13-28
Hiding Drawing Views	13-28
Modifying the Hatch Pattern of Section Views	13-28
Tutorial 1	13-28
Tutorial 2	13-35
Self-Evaluation Test	13-41
Review Questions	13-41
Exercise 1	13-42

Chapter 14: Working with the Drafting Workbench-II

Inserting Sheets in the Current File	14-2
Inserting the Frame and the Title Block	14-3
Automatic Insertion of the Frame and the Title Block	14-3
Creating the Frame and the Title Block Manually	14-5
Adding Annotations to the Drawing Views	14-7

Generating Dimensions	14-7
Adding Reference Dimensions	14-10
Adding Datum Features	14-12
Adding Geometric Tolerance to the Drawing Views	14-13
Adding Surface Finish Symbols	14-14
Adding Welding Symbols	14-15
Applying Weld	14-17
Editing Annotations	14-17
Generating the Bill of Material (BOM)	14-18
Generating Balloons	14-19
Tutorial 1	14-20
Tutorial 2	14-28
Self-Evaluation Test	14-32
Review Questions	14-33
Exercise 1	14-34

Chapter 15: Working with Sheet Metal Components

The Sheet metal Component	15-2
Starting a New File in Generative Sheet Metal Workbench	15-2
Setting Sheet Metal Parameters	15-3
Parameters Tab	15-3
Bend Extremities Tab	15-4
Bend Allowance Tab	15-6
Introduction to Sheet Metal Walls	15-6
Creating the Base Wall	15-6
Creating the Wall On Edge	15-7
Creating Extrusions	15-12
Creating Swept Walls	15-14
Creating Flanges on the Sheet Metal Component	15-14
Creating Hems on the Sheet Metal Component	15-17
Creating a Tear Drop on the Sheet Metal Component	15-17
Creating a User Flange on the Sheet Metal Component	15-18
Creating a Bend	15-19
Creating a Conical Bend	15-20
Bend From Flat	15-21
Creating Rolled Walls	15-24
Creating a Hopper Wall	15-24
Creating a Rolled Wall	15-26
Folding and Unfolding Sheet Metal Parts	15-26
Unfolding Sheet Metal Parts	15-27
Folding Unfolded Parts	15-27
Mapping the Geometry	15-29
Creating Flat Patterns of Sheet Metal Components	15-30
Viewing a Sheet Metal Component in Multiple Windows	15-30
Using Views Management	15-31
Stamping	15-31
Creating a Surface Stamp	15-32

Creating a Bead Stamp	15-35
Creating a Curve Stamp	15-36
Creating a Flanged Cut Out Stamp	15-38
Creating a Louver Stamp	15-39
Creating a Bridge Stamp	15-40
Creating a Flanged Hole Stamp	15-42
Creating a Circular Stamp	15-44
Creating a Stiffening Rib Stamp	15-45
Creating a Dowel Stamp	15-46
Tutorial 1	15-46
Tutorial 2	15-53
Tutorial 3	15-58
Tutorial 4	15-62
Self-Evaluation Test	15-68
Review Questions	15-69
Exercise 1	15-69

Chapter 16: DMU Kinematics

Introduction to DMU Kinematics	16-2
Designing a Mechanism	16-2
Creating the Revolute Joint	16-3
Creating the Prismatic Joint	16-8
Creating the Cylindrical Joint	16-9
Creating the Screw Joint	16-10
Creating the Rigid Joint	16-12
Creating the Spherical Joint	16-12
Creating the Planar Joint	16-15
Creating the Point Curve Joint	16-16
Creating the Slide Curve Joint	16-17
Creating the Roll Curve Joint	16-18
Creating the Point Surface Joint	16-19
Creating the Universal Joint	16-20
Creating the CV Joint	16-21
Creating the Gear Joint	16-22
Creating the Rack Joint	16-24
Creating the Cable Joint	16-26
Converting Assembly Constraints into Joints	16-27
Tutorial 1	16-28
Tutorial 2	16-34
Tutorial 3	16-40
Tutorial 4	16-47
Tutorial 5	16-51
Self-Evaluation Test	16-57
Review Questions	16-57
Exercise 1	16-58
Exercise 2	16-58

Chapter 17: Working with the FreeStyle Workbench

The FreeStyle Workbench	17-2
Starting a New FreeStyle File	17-2
Setting the FreeStyle Workbench	17-3
Creating Surfaces	17-5
Patches Sub-toolbar	17-5
Extrude Surface	17-8
Revolve	17-9
Offset	17-9
Styling Extrapolate	17-10
FreeStyle Blend Surface	17-11
Styling Fillet	17-13
Fills Sub-toolbar	17-14
Net Surface	17-15
Styling Sweep	17-16
Modifying Surfaces	17-16
Symmetry	17-17
Control Points	17-18
Match	17-21
Tutorial 1	17-27
Self-Evaluation Test	17-34
Review Questions	17-34
Exercise	17-35
Student Projects	1
Index	I-1