

Table of Contents

| | |
|---|------|
| Dedication | iii |
| Preface | xxi |
| Chapter 1: Introduction to SOLIDWORKS 2015 | |
| Introduction to SOLIDWORKS 2015 | 1-2 |
| Part Mode | 1-2 |
| Assembly Mode | 1-3 |
| Drawing Mode | 1-3 |
| System Requirements | 1-4 |
| Getting Started with SOLIDWORKS | 1-4 |
| Menu Bar and SOLIDWORKS Menus | 1-7 |
| CommandManager | 1-8 |
| Part Mode CommandManagers | 1-8 |
| Assembly Mode CommandManagers | 1-10 |
| Drawing Mode CommandManagers | 1-10 |
| Customized CommandManager | 1-11 |
| Toolbar | 1-11 |
| Pop-up Toolbar | 1-12 |
| View (Heads-Up) Toolbar | 1-12 |
| Shortcut Bar | 1-12 |
| Mouse Gestures | 1-13 |
| Dimensioning Standard and Units | 1-13 |
| Important Terms and Their Definitions | 1-13 |
| Feature-based Modeling | 1-13 |
| Parametric Modeling | 1-14 |
| Bidirectional Associativity | 1-14 |
| Windows Functionality | 1-15 |
| SWIFT Technology | 1-16 |
| Geometric Relations | 1-16 |
| Blocks | 1-18 |
| Library Feature | 1-18 |
| Design Table | 1-18 |
| Equations | 1-18 |
| Collision Detection | 1-18 |
| What's Wrong Functionality | 1-18 |
| 2D Command Line Emulator | 1-18 |
| SimulationXpress | 1-19 |
| Physical Dynamics | 1-19 |
| Physical Simulation | 1-19 |
| Seed Feature | 1-19 |
| FeatureManager Design Tree | 1-20 |
| Absorbed Features | 1-20 |

| | |
|---------------------------|------|
| Child Features | 1-20 |
| Dependent Features | 1-20 |
| Auto-Backup Option | 1-22 |
| Selecting Hidden Entities | 1-21 |
| Hot Keys | 1-21 |
| Color Scheme | 1-23 |
| Self-Evaluation Test | 1-23 |

Chapter 2: Drawing Sketches for Solid Models

| | |
|--|------|
| The Sketching Environment | 2-2 |
| Starting a New Session of SOLIDWORKS 2015 | 2-3 |
| Help customization Area | 2-3 |
| Task Panes | 2-4 |
| SOLIDWORKS Resources Task Pane | 2-4 |
| Design Library Task Pane | 2-5 |
| File Explorer Task Pane | 2-5 |
| View Palette Task Pane | 2-5 |
| Appearances, Scenes, and Decals Task Pane | 2-5 |
| Custom Properties Task Pane | 2-6 |
| SOLIDWORKS Forum Task Pane | 2-6 |
| Starting a New Document in SOLIDWORKS 2015 | 2-7 |
| Part | 2-7 |
| Assembly | 2-7 |
| Drawing | 2-7 |
| Understanding the Sketching Environment | 2-8 |
| Setting the Document Options | 2-10 |
| Modifying the Drafting Standards | 2-10 |
| Modifying the Linear and Angular Units | 2-11 |
| Modifying the Snap and Grid Settings | 2-13 |
| Learning Sketcher Terms | 2-14 |
| Origin | 2-14 |
| Inferencing Lines | 2-14 |
| Select Tool | 2-15 |
| Invert Selection Tool | 2-16 |
| Drawing Lines | 2-16 |
| Orientation Rollout | 2-17 |
| Options Rollout | 2-17 |
| Drawing Continuous Lines | 2-18 |
| Drawing Individual Lines | 2-19 |
| Line Cursor Parameters | 2-20 |
| Drawing Tangent or Normal Arcs Using the Line Tool | 2-20 |
| Drawing Construction Lines or Centerlines | 2-21 |
| Drawing Midpoint Line | 2-22 |
| Drawing the Lines of Infinite Length | 2-22 |

New

| | |
|--|------|
| Drawing Circles | 2-22 |
| Drawing Circles by Defining their Center Points | 2-23 |
| Drawing Circles by Defining Three Points | 2-23 |
| Drawing Construction Circles | 2-24 |
| Drawing Arcs | 2-24 |
| Drawing Tangent/Normal Arcs | 2-24 |
| Drawing Centerpoint Arcs | 2-26 |
| Drawing 3 Point Arcs | 2-27 |
| Drawing Rectangles | 2-27 |
| Drawing Rectangles by Specifying their Corners | 2-28 |
| Drawing Rectangles by Specifying the Center and a Corner | 2-28 |
| Drawing Rectangles at an Angle | 2-29 |
| Drawing Centerpoint Rectangles at an Angle | 2-29 |
| Drawing Parallelograms | 2-30 |
| Drawing Polygons | 2-31 |
| Drawing Splines | 2-32 |
| Drawing Slots | 2-33 |
| Creating a Straight Slot | 2-33 |
| Creating a Centerpoint Straight Slot | 2-34 |
| Creating a 3 Point Arc Slot | 2-34 |
| Creating a Centerpoint Arc Slot | 2-35 |
| Placing Sketched Points | 2-35 |
| Drawing Ellipses | 2-36 |
| Drawing Elliptical Arcs | 2-37 |
| Drawing Parabolic Curves | 2-38 |
| Drawing Conic Curves | 2-39 |
| Drawing Display Tools | 2-40 |
| Zoom to Fit | 2-40 |
| Zoom to Area | 2-40 |
| Zoom In/Out | 2-41 |
| Zoom to Selection | 2-41 |
| Pan | 2-41 |
| Previous View | 2-41 |
| Redraw | 2-42 |
| Deleting Sketched Entities | 2-42 |
| Tutorial 1 | 2-42 |
| Tutorial 2 | 2-47 |
| Tutorial 3 | 2-51 |
| Tutorial 4 | 2-55 |
| Self-Evaluation Test | 2-62 |
| Review Questions | 2-62 |
| Exercise 1 | 2-64 |
| Exercise 2 | 2-64 |
| Exercise 3 | 2-65 |
| Exercise 4 | 2-65 |

Chapter 3: Editing and Modifying Sketches

| | |
|---|------|
| Editing Sketched Entities | 3-2 |
| Trimming Sketched Entities | 3-2 |
| Extending Sketched Entities | 3-5 |
| Convert Entities | 3-6 |
| Intersection Curves | 3-6 |
| Filleting Sketched Entities | 3-7 |
| Chamfering Sketched Entities | 3-9 |
| Offsetting Sketched Entities | 3-10 |
| Mirroring Sketched Entities | 3-12 |
| Mirroring Entities Dynamically | 3-13 |
| Moving Sketched Entities | 3-13 |
| Rotating Sketched Entities | 3-15 |
| Scaling Sketched Entities | 3-17 |
| Stretching Sketched Entities | 3-17 |
| Copying and Pasting Sketched Entities | 3-19 |
| Creating Patterns | 3-19 |
| Creating Linear Sketch Patterns | 3-20 |
| Creating Circular Sketch Patterns | 3-23 |
| Editing Patterns | 3-25 |
| Writing Text in the Sketching Environment | 3-26 |
| Modifying Sketched Entities | 3-27 |
| Modifying a Sketched Line | 3-27 |
| Modifying a Sketched Circle | 3-27 |
| Modifying a Sketched Arc | 3-27 |
| Modifying a Sketched Polygon | 3-27 |
| Modifying a Spline | 3-28 |
| Modifying the Coordinates of a Point | 3-30 |
| Modifying an Ellipse or an Elliptical Arc | 3-30 |
| Modifying a Parabola | 3-30 |
| Dynamically Modifying and Copying Sketched Entities | 3-31 |
| Splitting Sketched Entities | 3-31 |
| Tutorial 1 | 3-32 |
| Tutorial 2 | 3-36 |
| Tutorial 3 | 3-41 |
| Self-Evaluation Test | 3-46 |
| Review Questions | 3-46 |
| Exercise 1 | 3-47 |
| Exercise 2 | 3-48 |
| Exercise 3 | 3-48 |
| Exercise 4 | 3-49 |
| Exercise 5 | 3-49 |
| Exercise 6 | 3-50 |

Chapter 4: Adding Relations and Dimensions to Sketches

| | |
|--|------|
| Applying Geometric Relations to Sketches | 4-2 |
| Applying Relations Using the Add Relations PropertyManager | 4-2 |
| Automatic Relations | 4-7 |
| Design Intent | 4-8 |
| Dimensioning a Sketch | 4-9 |
| Horizontal/Vertical Dimensioning | 4-11 |
| Aligned Dimensioning | 4-23 |
| Angular Dimensioning | 4-24 |
| Diameter Dimensioning | 4-25 |
| Radius Dimensioning | 4-26 |
| Linear Diameter Dimensioning | 4-26 |
| Ordinate Dimensioning | 4-27 |
| Concept of a Fully Defined Sketch | 4-28 |
| Fully Defined | 4-29 |
| Overdefined | 4-29 |
| Underdefined | 4-29 |
| Dangling | 4-29 |
| No Solution Found | 4-30 |
| Invalid Solution Found | 4-30 |
| Sketch Dimension or Relation Status | 4-30 |
| Deleting Overdefined Dimensions | 4-31 |
| Displaying and Deleting Relations | 4-33 |
| Opening an Existing File | 4-37 |
| Address Bar | 4-37 |
| File name | 4-38 |
| Type Drop-down List | 4-38 |
| Open Read-Only | 4-38 |
| Mode Drop-down List | 4-38 |
| Configurations | 4-39 |
| References | 4-39 |
| Quick Filter | 4-39 |
| Display States Drop-down List | 4-39 |
| Tutorial 1 | 4-40 |
| Tutorial 2 | 4-48 |
| Tutorial 3 | 4-54 |
| Self-Evaluation Test | 4-63 |
| Review Questions | 4-64 |
| Exercise 1 | 4-65 |
| Exercise 2 | 4-65 |
| Exercise 3 | 4-66 |

Chapter 5: Advanced Dimensioning Techniques and Base Feature Options

| | |
|---|------|
| Advanced Dimensioning Techniques | 5-2 |
| Fully Defining the Sketches | 5-2 |
| Dimensioning the True Length of an Arc | 5-4 |
| Measuring Distances and Viewing Section Properties | 5-4 |
| Measuring Distances | 5-5 |
| Determining the Section Properties of Closed Sketches | 5-7 |
| Creating Base Features by Extruding Sketches | 5-9 |
| Creating Solid Extruded Features | 5-9 |
| Creating Thin Extruded Features | 5-13 |
| Creating Base Features by Revolving Sketches | 5-15 |
| Creating Solid Revolved Features | 5-16 |
| Creating Thin Revolved Features | 5-18 |
| Determining the Mass Properties of Parts | 5-20 |
| Dynamically Rotating the View of a Model | 5-20 |
| Rotating the View Freely in 3D Space | 5-20 |
| Rotating the View around a Selected Vertex, Edge, or Face | 5-21 |
| Modifying the View Orientation | 5-21 |
| Changing the Orientation Using the Reference Triad | 5-23 |
| Restoring the Previous View | 5-24 |
| Displaying the Drawing Area in Viewports | 5-24 |
| Displaying the Drawing Area in Two Horizontal Viewports | 5-24 |
| Displaying the Drawing Area in Two Vertical Viewports | 5-24 |
| Displaying the Drawing Area in Four Viewports | 5-25 |
| Display Modes of a Model | 5-26 |
| Wireframe | 5-26 |
| Hidden Lines Visible | 5-26 |
| Hidden Lines Removed | 5-26 |
| Shaded With Edges | 5-26 |
| Shaded | 5-26 |
| Additional Display Modes | 5-26 |
| Shadows in Shaded Mode | 5-27 |
| Perspective | 5-27 |
| Assigning Materials and Textures to Models | 5-27 |
| Assigning Materials to a Model | 5-28 |
| Changing the Appearance of the Model | 5-29 |
| Editing the Appearances | 5-30 |
| Tutorial 1 | 5-31 |
| Tutorial 2 | 5-36 |
| Tutorial 3 | 5-40 |
| Self-Evaluation Test | 5-45 |
| Review Questions | 5-46 |
| Exercise 1 | 5-47 |
| Exercise 2 | 5-48 |
| Exercise 3 | 5-48 |

Chapter 6: Creating Reference Geometries

| | |
|---|------|
| Importance of Sketching Planes | 6-2 |
| Reference Geometry | 6-2 |
| Reference Planes | 6-3 |
| Creating New Planes | 6-4 |
| Creating Reference Axes | 6-10 |
| Creating Reference Points | 6-13 |
| Creating Reference Coordinate Systems | 6-15 |
| Creating Center of Mass | 6-15 |
| Advanced Boss/Base Options | 6-16 |
| Modeling Using the Contour Selection Method | 6-23 |
| Creating Cut Features | 6-26 |
| Creating Extruded Cuts | 6-27 |
| Creating Multiple Bodies in the Cut Feature | 6-30 |
| Creating Revolved Cuts | 6-32 |
| Concept of the Feature Scope | 6-32 |
| Tutorial 1 | 6-33 |
| Tutorial 2 | 6-38 |
| Tutorial 3 | 6-42 |
| Self-Evaluation Test | 6-49 |
| Review Questions | 6-49 |
| Exercise 1 | 6-51 |
| Exercise 2 | 6-53 |
| Exercise 3 | 6-53 |

Chapter 7: Advanced Modeling Tools-I

| | |
|---|------|
| Advanced Modeling Tools | 7-2 |
| Creating Simple Holes | 7-2 |
| Creating Standard Holes Using the Hole Wizard | 7-3 |
| Adding External Cosmetic Threads | 7-9 |
| Creating Fillets | 7-11 |
| Selection Options | 7-26 |
| Creating Fillets Using the FilletXpert | 7-28 |
| Creating Chamfers | 7-30 |
| Creating Shell Features | 7-33 |
| Creating Wrap Features | 7-36 |
| Tutorial 1 | 7-38 |
| Tutorial 2 | 7-46 |
| Tutorial 3 | 7-53 |
| Self-Evaluation Test | 7-62 |
| Review Questions | 7-62 |
| Exercise 1 | 7-63 |
| Exercise 2 | 7-64 |
| Exercise 3 | 7-65 |

Chapter 8: Advanced Modeling Tools-II

| | | |
|--|----------|------|
| Advanced Modeling Tools | | 8-2 |
| Creating Mirror Features | | 8-2 |
| Creating Linear Pattern Features | Enhanced | 8-6 |
| Creating Circular Pattern Features | | 8-12 |
| Creating Sketch Driven Patterns | | 8-14 |
| Creating Curve Driven Patterns | | 8-15 |
| Creating Table Driven Patterns | | 8-17 |
| Creating Fill Patterns | | 8-19 |
| Creating Variable Patterns | New | 8-22 |
| Creating Rib Features | | 8-23 |
| Displaying the Section View of a Model | | 8-28 |
| Changing the Display States | | 8-30 |
| Tutorial 1 | | 8-31 |
| Tutorial 2 | | 8-39 |
| Tutorial 3 | | 8-43 |
| Self-Evaluation Test | | 8-54 |
| Review Questions | | 8-54 |
| Exercise 1 | | 8-56 |
| Exercise 2 | | 8-57 |
| Exercise 3 | | 8-58 |
| Exercise 4 | | 8-59 |

Chapter 9: Editing Features

| | | |
|--|--|------|
| Editing the Features of a Model | | 9-2 |
| Editing Using the Edit Feature Tool | | 9-2 |
| Editing Sketches of the Sketch-based Features | | 9-3 |
| Editing the Sketch Plane Using the Edit Sketch Plane Tool | | 9-3 |
| Editing Using the Instant3D Tool | | 9-4 |
| Editing Features and Sketches by Using the Cut, Copy, and Paste Options | | 9-7 |
| Cutting, Copying, and Pasting Features and Sketches from One Document to the Other | | 9-8 |
| Copying Features Using Drag and Drop | | 9-8 |
| Deleting Features | | 9-9 |
| Deleting Bodies | | 9-10 |
| Suppressing Features | | 9-11 |
| Unsuppressing the Suppressed Features | | 9-11 |
| Unsuppressing Features with Dependents | | 9-11 |
| Hiding Bodies | | 9-12 |
| Moving and Copying Bodies | | 9-12 |
| Reordering the Features | | 9-15 |
| Rolling Back the Feature | | 9-15 |
| Renaming Features | | 9-16 |
| Creating Folders in the FeatureManager Design Tree | | 9-16 |
| What's Wrong Functionality | | 9-17 |

| | |
|----------------------|------|
| Tutorial 1 | 9-18 |
| Tutorial 2 | 9-25 |
| Tutorial 3 | 9-29 |
| Self-Evaluation Test | 9-35 |
| Review Questions | 9-36 |
| Exercise 1 | 9-36 |
| Exercise 2 | 9-38 |

Chapter 10: Advanced Modeling Tools-III

| | |
|------------------------------------|-------|
| Advanced Modeling Tools | 10-2 |
| Creating Sweep Features | 10-2 |
| Creating Cut-Sweep Features | 10-12 |
| Creating Loft Features | 10-14 |
| Adding a Section to a Loft Feature | 10-21 |
| Creating Lofted Cuts | 10-23 |
| Creating 3D Sketches | 10-23 |
| Creating Grid Systems | 10-25 |
| Editing 3D Sketches | 10-27 |
| Creating Curves | 10-27 |
| Extruding a 3D Sketch | 10-37 |
| Creating Draft Features | 10-38 |
| Tutorial 1 | 10-42 |
| Tutorial 2 | 10-45 |
| Tutorial 3 | 10-49 |
| Self-Evaluation Test | 10-54 |
| Review Questions | 10-54 |
| Exercise 1 | 10-56 |
| Exercise 2 | 10-57 |
| Exercise 3 | 10-58 |

Chapter 11: Advanced Modeling Tools-IV

| | |
|-------------------------------|-------|
| Advanced Modeling Tools | 11-2 |
| Creating Dome Features | 11-2 |
| Creating Indents | 11-5 |
| Creating Deform Features | 11-8 |
| Creating Flex Features | 11-12 |
| Creating Fastening Features | 11-16 |
| Creating the Mounting Boss | 11-16 |
| Creating Snap Hooks | 11-18 |
| Creating Snap Hook Grooves | 11-21 |
| Creating Vents | 11-22 |
| Creating a Lip/Groove Feature | 11-27 |
| Creating Freeform Features | 11-30 |
| Face Settings Rollout | 11-32 |
| Control Curves Rollout | 11-32 |

| | |
|--|-------|
| Control Points Rollout | 11-32 |
| Display Rollout | 11-33 |
| Dimensioning a Part Using DimXpert | 11-34 |
| Specifying the Datum | 11-34 |
| Pop-up Toolbar | 11-35 |
| Adding Dimensions | 11-36 |
| Specifying the Location of a Feature | 11-37 |
| Adding Geometric Tolerance to the Features | 11-38 |
| Collecting Pattern Features | 11-40 |
| Adding Dimensions Automatically | 11-40 |
| Tutorial 1 | 11-41 |
| Tutorial 2 | 11-45 |
| Tutorial 3 | 11-48 |
| Tutorial 4 | 11-52 |
| Self-Evaluation Test | 11-58 |
| Review Questions | 11-59 |
| Exercise 1 | 11-60 |

Chapter 12: Assembly Modeling-I

| | |
|--|-------|
| Assembly Modeling | 12-2 |
| Types of Assembly Design Approach | 12-2 |
| Creating Bottom-up Assemblies | 12-3 |
| Placing Components in the Assembly Document | 12-4 |
| Assembling Components | 12-8 |
| Creating Top-down Assemblies | 12-27 |
| Creating Components in the Top-down Assembly | 12-27 |
| Moving Individual Components | 12-28 |
| Moving Individual Components by Dragging | 12-28 |
| Moving Individual Components Using the Move Component Tool | 12-28 |
| Rotating Individual Components | 12-29 |
| Rotating Individual Components by Dragging | 12-29 |
| Rotating Individual Components Using the Rotate Component Tool | 12-30 |
| Moving and Rotating Individual Components Using the Triad | 12-30 |
| Assembly Visualization | 12-32 |
| Tutorial 1 | 12-33 |
| Tutorial 2 | 12-45 |
| Self-Evaluation Test | 12-50 |
| Review Questions | 12-51 |
| Exercise 1 | 12-52 |
| Exercise 2 | 12-54 |
| Exercise 3 | 12-58 |

Chapter 13: Assembly Modeling-II

| | | |
|---|----------|-------|
| Advanced Assembly Mates | Enhanced | 13-2 |
| Applying the Profile Center Mate | | 13-2 |
| Applying the Symmetric Mate | | 13-3 |
| Applying the Width Mate | | 13-3 |
| Applying the Distance Mate | | 13-4 |
| Applying the Angle Mate | | 13-5 |
| Applying the Path Mate | | 13-5 |
| Mechanical Mates | Enhanced | 13-6 |
| Applying the Cam Mate | | 13-6 |
| Applying the Slot Mate | | 13-7 |
| Applying the Hinge Mate | | 13-8 |
| Applying the Gear Mate | | 13-9 |
| Applying the Rack Pinion Mate | | 13-10 |
| Applying the Screw Mate | | 13-10 |
| Creating Sub-assemblies | | 13-10 |
| Bottom-up Sub-assembly Design Approach | | 13-11 |
| Top-down Sub-assembly Design Approach | | 13-11 |
| Inserting a New Sub-assembly | | 13-12 |
| Deleting Components and Sub-assemblies | | 13-12 |
| Editing Assembly Mates | | 13-12 |
| Replacing Mated Entities | | 13-13 |
| Editing Components | | 13-14 |
| Editing Sub-assemblies | | 13-15 |
| Dissolving Sub-assemblies | | 13-15 |
| Replacing Components | | 13-16 |
| Creating Patterns of Components in an Assembly | | 13-18 |
| Pattern Driven Component Pattern | | 13-18 |
| Local Pattern | | 13-20 |
| Copying and Mirroring Components | | 13-21 |
| Copying a Component along with Mates | | 13-22 |
| Simplifying Assemblies using the Visibility Options | | 13-23 |
| Hiding Components | | 13-24 |
| Suppressing and Unsuppressing the Components | | 13-24 |
| Changing the Transparency Conditions | | 13-24 |
| Changing the Display States | | 13-25 |
| Checking Interferences in an Assembly | | 13-25 |
| Checking the Hole Alignment | | 13-26 |
| Creating Assemblies for Mechanism | | 13-27 |
| Analyzing Collisions Using the Collision Detection Tool | | 13-28 |
| Creating the Exploded State of an Assembly | Enhanced | 13-30 |
| Creating the Explode Line Sketch | | 13-33 |
| Tutorial 1 | | 13-34 |
| Tutorial 2 | | 13-47 |
| Self-Evaluation Test | | 13-51 |
| Review Questions | | 13-52 |
| Exercise 1 | | 13-53 |

Chapter 14: Working with Drawing Views-I

| | |
|---|-------|
| The Drawing Mode | 14-2 |
| Starting a Drawing Document | 14-2 |
| Starting a New Drawing Document Using the New SOLIDWORKS Document Dialog Box | 14-2 |
| Starting a New Drawing Document from the Part/Assembly Document | 14-4 |
| Types of Views | 14-5 |
| Model View | 14-5 |
| Projected View | 14-5 |
| Section View | 14-5 |
| Aligned Section View | 14-5 |
| Auxiliary View | 14-5 |
| Detail View | 14-5 |
| Broken View | 14-5 |
| Broken-out Section View | 14-6 |
| Crop View | 14-6 |
| Alternate Position View | 14-6 |
| Generating Standard Drawing Views | 14-6 |
| Generating Model Views | 14-6 |
| Using the View Palette to Place the Drawing Views | 14-8 |
| Generating the Three Standard Views | 14-9 |
| Generating Standard Views Using the Relative View Tool | 14-10 |
| Generating Standard Views Using the Predefined View Tool | 14-12 |
| Generating Derived Views | 14-14 |
| Generating Projected Views | 14-14 |
| Generating Section Views | 14-15 |
| Generating Broken-out Section Views | 14-23 |
| Generating Auxiliary Views | 14-25 |
| Generating Detail Views | 14-26 |
| Generating Crop Views | 14-29 |
| Generating Broken Views | 14-29 |
| Generating Alternate Position Views | 14-31 |
| Generating Drawing Views of the Exploded State of an Assembly | 14-33 |
| Working with Interactive Drafting in SOLIDWORKS | 14-33 |
| Editing and Modifying Drawing Views | 14-34 |
| Changing the View Orientation | 14-34 |
| Changing the Scale of Drawing Views | 14-34 |
| Deleting Drawing Views | 14-34 |
| Rotating Drawing Views | 14-34 |
| Manipulating the Drawing Views | 14-35 |
| Modifying the Hatch Pattern in Section Views | 14-35 |
| Properties Rollout | 14-35 |
| Options Rollout | 14-36 |
| Tutorial 1 | 14-37 |
| Tutorial 2 | 14-42 |
| Self-Evaluation Test | 14-47 |
| Review Questions | 14-48 |
| Exercise 1 | 14-49 |

Chapter 15: Working with Drawing Views-II

| | |
|---|-------|
| Adding Annotations to Drawing Views | 15-2 |
| Generating Annotations Using the Model Items Tool | 15-2 |
| Adding Reference Annotations | 15-4 |
| Aligning the Dimensions | 15-20 |
| Editing Annotations | 15-20 |
| Adding the Bill of Materials (BOM) to a Drawing | 15-21 |
| Table Template Rollout | 15-21 |
| Table Position Rollout | 15-21 |
| BOM Type Rollout | 15-21 |
| Configurations Rollout | 15-22 |
| Part Configuration Grouping Rollout | 15-23 |
| Keep Missing Item Rollout | 15-23 |
| Item Numbers Rollout | 15-23 |
| Border Rollout | 15-24 |
| Setting Anchor Point for the BOM | 15-24 |
| Linking Bill of Materials | 15-24 |
| Adding Balloons to the Drawing Views | 15-24 |
| Adding Balloons Using the AutoBalloon Tool | 15-25 |
| Creating Magnetic Lines | 15-27 |
| Adding New Sheets to the Drawing Views | 15-28 |
| Editing the Sheet Format | 15-29 |
| Creating User-Defined Sheet Formats | 15-29 |
| Tutorial 1 | 15-30 |
| Tutorial 2 | 15-36 |
| Self-Evaluation Test | 15-41 |
| Review Questions | 15-42 |
| Exercise 1 | 15-43 |

Chapter 16: Surface Modeling

| | |
|------------------------------|-------|
| Surface Modeling | 16-2 |
| Creating an Extruded Surface | 16-2 |
| Creating a Revolved Surface | 16-3 |
| Creating a Swept Surface | 16-4 |
| Creating a Lofted Surface | 16-7 |
| Creating a Boundary Surface | 16-9 |
| Creating a Planar Surface | 16-13 |
| Creating a Fill Surface | 16-14 |
| Creating a Radiated Surface | 16-18 |
| Offsetting Surfaces | 16-19 |
| Trimming Surfaces | 16-20 |
| Untrimming Surfaces | 16-23 |
| Extending Surfaces | 16-26 |
| Knitting Surfaces | 16-28 |
| Filleting Surfaces | 16-29 |

| | |
|------------------------------------|-------|
| Creating a Mid-Surface | 16-30 |
| Deleting Holes from Surfaces | 16-31 |
| Replacing Faces | 16-32 |
| Deleting Faces | 16-33 |
| Moving and Copying Surfaces | 16-35 |
| Mirroring Surface Bodies | 16-35 |
| Adding Thickness to Surface Bodies | 16-35 |
| Creating a Thicken Surface Cut | 16-37 |
| Creating a Surface Cut | 16-38 |
| Tutorial 1 | 16-38 |
| Tutorial 2 | 16-48 |
| Self-Evaluation Test | 16-58 |
| Review Questions | 16-59 |
| Exercise 1 | 16-60 |
| Exercise 2 | 16-61 |

Chapter 17: Working with Blocks

| | |
|--|-------|
| Introduction to Blocks | 17-2 |
| Blocks Toolbar | 17-2 |
| Saving a Sketch as a Block in the Design Library | 17-7 |
| Creating Mechanisms by Using Blocks | 17-8 |
| Creating the Rack and Pinion Mechanism | 17-8 |
| Creating the Cam and Follower Mechanism | 17-9 |
| Applying Motion to Blocks | 17-11 |
| Creating Parts from Blocks | 17-12 |
| Selected Blocks | 17-12 |
| Block to Part Constraint | 17-12 |
| Tutorial 1 | 17-13 |
| Tutorial 2 | 17-21 |
| Self-Evaluation Test | 17-28 |
| Review Questions | 17-28 |
| Exercise 1 | 17-29 |

Chapter 18: Sheet Metal Design

| | |
|--|-------|
| Sheet Metal Design | 18-2 |
| Designing the Sheet Metal Components by Creating the Base Flange | 18-2 |
| Creating the Base Flange | 18-3 |
| Understanding the FeatureManager Design Tree of a Sheet Metal Component | 18-6 |
| Creating the Edge Flange | 18-7 |
| Creating Tabs | 18-15 |
| Creating the Sketched Bend | 18-16 |
| Creating the Miter Flange | 18-18 |
| Creating Closed Corners | 18-20 |
| Creating Hems | 18-22 |

| | |
|---|-------|
| Creating the Jog Bend | 18-24 |
| Breaking the Corners | 18-27 |
| Creating the Swept Flange | 18-28 |
| Creating Cuts on the Planar Faces of the Sheet Metal Components | 18-29 |
| Creating Lofted Bends | 18-30 |
| Creating a Flat Pattern View of the Sheet Metal Components | 18-30 |
| Creating Sheet Metal Components from a Flat Sheet | 18-33 |
| Creating a Sheet Metal Component from a Flat Part | 18-34 |
| Converting a Part or a Flat Part into Sheet Metal by Adding Bends | 18-34 |
| Adding Bends to the Flattened Sheet Metal Component | 18-35 |
| Unbending the Sheet Metal Part Using the No Bends Tool | 18-36 |
| Creating a Sheet Metal Component by Designing it as a Part | 18-37 |
| Types of Bends | 18-38 |
| Converting a Solid Body into a Sheet Metal Part | 18-39 |
| Designing a Sheet Metal Part from a Solid Shelled Model | 18-41 |
| Ripping the Edges | 18-41 |
| Creating Cuts in Sheet Metal Components Across the Bends | 18-42 |
| Creating Cuts in a Sheet Metal Component Created from a Solid Model | 18-43 |
| Creating Cuts in a Sheet Metal Component Created Using the Base Flange | 18-44 |
| Creating Cylindrical and Conical Sheet Metal Components | 18-45 |
| Inserting Forming Tools | 18-46 |
| Creating Forming Tools | 18-48 |
| Generating the Drawing View of the Flat Pattern of the Sheet Metal Components | 18-48 |
| Tutorial 1 | 18-49 |
| Tutorial 2 | 18-56 |
| Self-Evaluation Test | 18-65 |
| Review Questions | 18-66 |
| Exercise 1 | 18-67 |

Chapter 19: Equations, Configurations, and Library Features

| | |
|---|-------|
| Working with Equations | 19-2 |
| Adding Global Variables | 19-4 |
| Suppressing and Unsuppressing Features | 19-6 |
| Adding Equations | 19-7 |
| Editing Equations | 19-8 |
| Deleting Equations | 19-9 |
| Exporting/Importing Equations | 19-9 |
| Working with Configurations | 19-9 |
| Creating Configurations Manually | 19-9 |
| Editing the Features of a Part with Multiple Configurations | 19-11 |
| Creating Configurations by Using Design Tables | 19-12 |
| Changing the Suppression State by Using the Design Table | 19-16 |
| Editing the Design Table | 19-19 |
| Deleting the Design Table | 19-20 |
| Changing the Suppression State of a Component without Invoking the Design Table | 19-20 |

| | |
|---|-------|
| Changing the Visibility of Components in Different Configurations of an Assembly | 19-21 |
| Library Features | 19-22 |
| Creating a Library Feature | 19-22 |
| Placing Library Features in a Part | 19-23 |
| Editing the Library Features | 19-25 |
| Dissolving the Library Features | 19-26 |
| Tutorial 1 | 19-26 |
| Tutorial 2 | 19-30 |
| Self-Evaluation Test | 19-33 |
| Review Questions | 19-33 |
| Exercise 1 | 19-34 |
| Exercise 2 | 19-35 |
| Exercise 3 | 19-35 |

Chapter 20: Motion Study

| | |
|--------------------------------------|-------------|
| Introduction To Motion Study | 20-2 |
| Simulating the Motion of an Assembly | 20-2 |
| Timeline | 20-2 |
| Timebar | 20-2 |
| Keypoint | 20-3 |
| MotionManager Design Tree | 20-3 |
| Toolbar | 20-3 |
| Tutorial 1 | 20-15 |
| Tutorial 2 | 20-17 |
| Self-Evaluation Test | 20-20 |
| Review Questions | 20-20 |
| Exercise 1 | 20-21 |
| Exercise 2 | 20-22 |
| Student Projects | SP-1 |
| Index | I-1 |